
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/30/2009
Test to be performed: Smoke Dyed Water X Dry ✓ Damp ☐ Wet ☐		Supervisor: <u>JAW</u>
Manhole_ID: S01UU_021MH	Test ID: <u>D1032-025017</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S01UU_021MH
0			Start of Survey	
0			Water Level	
3			Dye Test Visible	dye seen at joint
6			Dye Test Visible	dte seen at joint
13.69999981			Dye Test Visible	dye seen at joint
16.60000038			Dye Test Visible	dye seen at joint
22.70000076			Dye Test Visible	dye seen at joint
46.79999924			Manhole	S01UU_009MH
46.79999924			End of Survey	